

HAER
NH,
5-CAMPHO,
1-

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Osgood Bridge
Spanning the Beebe River on Perch Pond Road,
just south of the hamlet of Campton Hollow
Town of Campton
Grafton County
New Hampshire

HAER No. NH-10

Photographer: Ernest Gould, Hooksett, N. H., for Closs Planners Inc.
November 1986

- NH-10-1 View west, east elevation spanning Beebe River
- NH-10-2 View southwest, east low Warren truss
- NH-10-3 View northwest, south approach and east truss; railing detail
- NH-10-4 View north, looking through truss; wooden deck railing detail
- NH-10-5 View east, west elevation spanning Beebe River
- NH-10-6 View northeast, low Warren truss and north and south granite abutments
- NH-10-7 View southeast, west low Warren truss
- NH-10-8 View south, looking through truss; wooden guardrail and bridge deck
- NH-10-9 View southwest, south abutment and east truss
- NH-10-10 View northwest, bridge manufacturer's plate and reinforced haunch
- NH-10-11 View northwest, lower chord and typical panel connections
- NH-10-12 View southwest, typical panel and x-member connections, lower chord
- NH-10-13 View southeast, upper chord splice (typical)
- NH-10-14 View west, truss web and inclined end post details
- NH-10-15 View northwest, (east) truss web; vertical members detail
- NH-10-16 View west, typical floor beam at lower chord panel connection
- NH-10-17 View north, north abutment; x-members below bridge floor system
- NH-10-18 View south, south abutment, x-members below bridge floor system

Osgood Bridge
HAER No. NH-10 (Page 2)
Index to Photographs

- NH-10-19 View east, southwest bridge bearing detail (typical)
- NH-10-20 View north, north abutment and east wingwall
- NH-10-21 View southwest, south abutment and east and west wingwalls
- NH-10-22 View west, iron dowel repair, north abutment, courses 5 and 6
- NH-10-23 View south, town officials plate